Regency
the first name in solid state

PROFESSIONAL
2 WAY action radio

DATE 7/6/82

SSC Service Bulletin

no. 82-255

TO: REGENCY COMMUNICATIONS PROFESSIONAL SALES & SERVICE CENTERS

REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: XLHC252, XLHC257

PROBLEM: INCORRECTLY LABELED PART ON PARTS PLACEMENT DIAGRAM

CURE:

Re-label C428 as C421 on Parts Placements Diagram in the respective Service Manuals - Figure 4-3B (XLHC252) and Figure 5-7b (XLHC257).

TECHNICAL SERVICE DEPARTMENT

REGENCY COMMUNICATIONS, INC.